

1st June 2016

Service Charges

DESCRIPTION	MRSP EX. TAXES
AF Calibration	€300
Aux Shutter Drive Unit Replacement	€620
Aux Shutter Replacement	€730
Body Contact Replacement	€545
EU Replacement, HC35/HC50/HC80/HC100	€1,100
EU Replacement, HCD28/HC120/HC150/HC210	€1,350
EU Replacement, HCD24/HC300/HC50-110/HCD35-90	€1,550
Exposure Button Replacement	€175
Eye Cup Replacement (long or short)	€90
Focus Mechanism Overhaul	€210
Mainboard Replacement, H Body	€925
Mirror Drive Unit Replacement	€720

DESCRIPTION	MRSP EX. TAXES
Sensor Cleaning, Legacy (16 - 39MP)	€725
Sensor Cleaning CCD 40/50/60MP	€650
Sensor Cleaning CMOS 50MP	€695
Sensor cleaning CMOS 100MP	€795
CPU Board Replacement, H6D-50c	€1,905
Display Replacement, H4D	€1220
Display Replacement, H5D	€1225
Display Replacement, H6D	€1650
DSP Board Replacement, H5D	€2,050
DSP Board Replacement, H4D-40/50	€1,995
DSP Board Replacement, H4D-60	€2,415
DSP Board Replacement, Legacy (16-39)	€1,995
Link Board Replacement, H3DII, H4D40/50	€940
Link Board Replacement, H4D-60	€950
Link Board Replacement, H5D-40/50/60, CFV-50	€950
Link Board Replacement, H5D-50c & CFV-50c	€950
Piezo Calibration, Multi-shot	€520
Piezo Exchange, Multi-shot	€1,850
Sensor Replacement, H4D-40/H5D-40	€6,425
Sensor Replacement, H4D-50/H5D-50/50MS/200MS	€7,330
Sensor Replacement, H5D-50c/50MSc/200MSc	€8,030
Sensor Replacement, H4D-60/H5D-60	€8,195
Sensor Replacement, H6D-50C	€8,645
Sensor Replacement, Legacy (16-39 MP)	€3,870
Support Board Replacement, H6D-50C	€995