HASSELBLAD

CREATE TO INSPIRE

FIRMWARE 1.0.2 FOR HASSELBLAD X1D II 50C

The 1.0.2 firmware is an important bug fix and stability improvement firmware release for the X1D II 50C camera. We strongly recommend all users to update.

STABILITY IMPROVEMENTS AND BUG FIXES COMPARED TO V1.0.1:

- General system stability
- Phocus Tethering stability

UPDATE PROCEDURE

Make sure that you use a fully charged battery for the update. A charge level of 50% or more is required. Please note that the update procedure normally takes about 7-10 minutes, but can in some cases take up to 12 minutes.

IMPORTANT NOTES

- Wait until the message "Update is Completed" is shown.

Copy the downloaded file (X1D_II_50C_v1_0_2.cim) directly to the SD card (not into a folder) and insert it into the camera. Then follow the procedure below:

1: Select the "General Settings Menu" from the main menu.

2: Select "Service".

3: Click "Check for Update" and select the file "X1D_II_50C_v1_0_2.cim" from the list. Finally, click "Update".

November 2019 / Hasselblad